




4.32 Temperature-composition phase diagrams for A+B mixtures and A+C mixtures.



Ternary diagram for mixtures of A+B+C at a particular temperature.



Blank ternary diagram.



from *Chemical Engineering Design and Analysis: An Introduction*
T. M. Duncan and J. A. Reimer, Cambridge University Press, 2nd ed., 2019.