


4.91 phase diagram for $P+Q$ mixtures at 1 atm.



from *Chemical Engineering Design and Analysis: An Introduction*
T. M. Duncan and J. A. Reimer, Cambridge University Press, 2nd ed., 2019.

©Cambridge University Press.